



POLISHED CONCRETE MAINTENANCE

3DC objective is to provide its customers with a product that requires little ongoing maintenance. Please note that the finished surface may initially have a slight waxy appearance that will disappear after approximately 6 washes.

Your finished polished concrete floor can be walked on the next day however it must be kept dry for 3 days.

The floor should be maintained on a regular basis by vacuuming and cleaning in the following manner:

- To a bucket of warm water, add recommended amount of cleaner (or low ph cleaner) and mop floor with a microfibre mop. The floor should be damp for the shortest possible time. This will leave the floor clean and streak free. This simple cleaning should be carried out to keep the floor looking its best.

CAUTION: Concrete floors may be slippery, particularly when wet. Do not use any buffing type machine or product other than specified, as any type of abrasive cleaner will dull the surface.

Periodical Maintenance

Low traffic areas/Residential

- Depending on the surrounding environment these areas will require a burnish using a high speed burnisher with 3500 buffing pads, only when necessary.

High traffic areas/Commercial

- Burnish on a regular basis with a high speed burnisher with 3500 buffing pads to maintain a high gloss surface.

Caution: Do not use bleach or citrus based cleaners.

Simple tips: Fit protective pads to chairs & tables. Castor legs should be fitted into castor cups. Use a dry mop regularly. Avoid direct heat from free standing heaters. Spills should be cleaned up immediately to avoid penetration or damage.